

Photographs to accompany LHI bid 2024-5



Photo A Looking east from entry/exit of G&D car park towards junction with Duncock Lane with cars part parking on footpath on north side of Boxworth Rd. (10/12/23). Note no footpath on south side.



Photo B Looking westwards on Boxworth Rd. from junction with Roger's Close with cars less than 10m from junction. (07/01/24)



Photo C Looking westwards from junction with Duncock Lane with cars part parked on footpath and showing camber of footpath (11/12/22). Problem persists as shown at photos A and D.



Photo D As C car parked less than 10m from junction with Duncock Lane (14/12/22)



Photo E Car exiting Duncock Lane with visibility impacted by car parked less than 10m from junction. (07/12/23)



Photo F As photos C and but taken a year later. (01/12/23)